EAST Search History

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	~ ,	· passassassassassassassassassassassassass	·	300000000000000000000000000000000000000	200000000000000000000000000000000	
Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	239	(219/86.1). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 10:34
S2	156	(219/90).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 10:36
S3	862	(219/119).OCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 10:36
S4	129603	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 10:38
S5	2	S1 and ((weld\$3 near5 (resistance or spot) near50 electrode\$1 near50 (strip\$1 or sheet\$1 or foil \$1) near50 (protect\$3 or wear\$3 or cover \$3 or damag\$3 or distort\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16
S 6	20	S1 and ((weld\$3 near5 (resistance or spot) near50 electrode\$1 near50 (strip\$1 or sheet\$1 or foil \$1 or protect\$3 or wear\$3 or cover\$3 or damag\$3 or distort\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 10:40

S 7	146	((weld\$3 near5 (resistance or spot) near50 electrode\$1 near50 (strip\$1 or sheet\$1 or foil \$1) near50 (protect\$3 or wear\$3 or cover \$3 or damag\$3 or distort\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 10:48
S8	615	((weld\$3 near50 electrode\$1 near50 (strip\$1 or sheet\$1 or foil \$1) near50 (protect\$3 or wear\$3 or cover \$3 or damag\$3 or distort\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 11:02
S9	216	((weld\$3 near50 electrode\$1 near50 (metal\$2 or alloy) near10 (strip\$1 or sheet \$1 or foil\$1) near50 (protect \$3 or wear\$3 or cover\$3 or damag\$3 or distort\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 11:03
S10	153	((weld\$3 near10 electrode\$1 near10 (metal\$2 or alloy) near10 (strip\$1 or sheet \$1 or foil\$1) near50 (protect \$3 or wear\$3 or cover\$3 or damag\$3 or distort\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/08/16 11:03

S11	17	((weld\$3 near10 electrode\$1 near10 (metal\$2 or alloy) near10 (strip\$1 or sheet \$1 or foil\$1) near50 (protect \$3 or wear\$3 or cover\$3 or damag\$3 or distort\$3))).clm.	US-PGPUB; USPAT	OR	OFF	2008/08/16 11:11
S12	25	((weld\$3 near50 electrode\$1 near50 (metal\$2 or alloy) near50 (strip\$1 or sheet \$1 or foil\$1) near50 (protect \$3 or wear\$3 or cover\$3 or distort\$3)).clm.	US-PGPUB; USPAT	OR	OFF	2008/08/16 11:12
S13	53	(((weld\$3 near50 electrode\$1 near50 (strip\$1 or sheet\$1 or foil \$1) near50 (protect\$3 or wear\$3 or cover \$3 or damag\$3 or distort\$3))). clm.	US-PGPUB; USPAT	OR	OFF	2008/08/16 11:13

8/16/08 11:16:35 AM

C:\ Documents and Settings\ kkerns\ My Documents\ EAST\ Workspaces\ 10519873(219) rcerce.wsp